



NFTAC

NATIONAL FIREBIRD & T/A CLUB

TECHNICAL SECTIONS Vol. II

ON CD-ROM

Reprints from the 1998 thru 2007 NFTAC *EAGLE*

Volume I, covering earlier publications also available from the NFTAC

**PUBLISHED BY THE NFTAC
P. O. BOX 11238, CHICAGO, IL 60611 U.S.A.**

Phone: (773) 769-6262

FAX: (773) 769-3240

email: tech@firebirdtaclub.com

web site: firebirdtaclub.com or www.firebirdclub.net

NFTAC TECHNICAL SECTIONS

<u>PUBLICATION</u>	<u>PAGE</u>
February 1998	10
August 1998	15
November 1998	23
February 1999	25
May 1999	30
November 1999	39
February 2000	43
May 2000	49
August 2000	55
November 2000	60
February 2001	63
May 2001	67
August 2001	70
November 2001	73
February 2002	78
May 2002	83
August 2002	88
November 2002	93
February 2003	97
May 2003	100
August 2003	107
January 2004	114
May 2004	119
August 2004	123
November 2004	130
February 2005	134
May 2005	138
August 2005	142
January 2006	144
May 2006	146
August 2006	148
November 2006	150
February 2007	154
May 2007	158
August 2007	160

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the express written consent of the publisher. The views of contributing writers are their own and not necessarily the views of the NFTAC. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the NFTAC.

Copyright © 2007, NFTAC

ARTICLE INDEX

Publication references in which AMGBA publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q & A), its position on the page and page number in this issue.

SUBJECT/ ARTICLE	ISSUE	ORIGINAL PUBLICATION		PAGE NUMBER
		PAGE	Q & A	THIS ISSUE
Brakes				
Adjusting rear discs	2002 November	33	3	95
Brakes shaking steering wheel	2000 May	35	1	54
Drum to disc brakes	2002 November	33	1	95
Parking brake	2002 November	29	1	97
Carburetion/Fuel System				
'72 hood air scoop	1999 May	34		35
Aftermarket ram air system	2000 August	32	3	57
Air intake tube	2004 August	32	1	126
Airflow sensor screen	2000 August	29	6	56
Black residue	2006 August	26	1	149
Carb size	2005 August	22	1	143
Cold air induction	1998 November	29	1	24
Fried fuel pump	2000 August	29	3	56
Fuel injector replacement	2001 May	32	1	68
Gasoline vapor smell	1999 May	29	3	33
Gas smell	1998 November	29	2	24
Intake manifold/scoop	2006 May	22	2	146
Ram air intake modification	2007 August	22	2	160
Stalling	2005 May	23	1	139
Stock throttle body	2001 August	32	1	70
Surging	2005 August	21	5	142
TPI Installation	2001 February	29	4	64
Tripower installation	2002 May	29	4	84
Wrong gas	2000 November	32	3	61
Cooling and Heating Systems				
'79 carb fit	2000 May	29	2	50
AC recharging	2003 August	29	5	110
AC removal	2001 November	28	2	73
Cracked heater core	2005 May	23	3	139
Downshift control cable	2001 November	28	3	73
Cooling fans	2005 August	21	4	142
Heater blower	2002 February	32	4	80
Heater core leakage	2003 February	32	1	98
Heater core replacement	2000 May	28	2	49
Heater core removal	2002 February	28	1	78
Low pressure AC port	2002 February	29	2	79

SUBJECT/ ARTICLE	ISSUE	ORIGINAL PUBLICATION		PAGE NUMBER
		PAGE	Q & A	THIS ISSUE
Overheating	1999 November	25	6	39
Overheating	2001 February	32		65
Overheats	1999 November	25	4	39
Radiator hose collapse	2004 November	26	1	133
Running hot	2000 November	29	2	60
Running hot with AC on	2004 January	34		118
Temperature sending unit	2003 August	33	4	112
Water temperature	2000 August	29	2	56
Windshield defroster	2003 August	29	1	110
Electrical				
'06 & '97 headlight doors	2000 August	33		58
2nd gear start switch	2000 May	28	1	49
32 amp alternator installation	2003 May	32	1	104
4th generation headlight fix	2002 May	33		86
'88 digital dash	2003 May	28	6	102
Another headlight fix	2002 May	34		92
Computer checks	1998 August	29	2	19
ESM reset	2000 February	29		46
Electrical system transfer	1999 May	32	2	34
Firing order	2002 February	32	3	80
Headlight door noise	2002 November	34		96
Headlights	1999 February	34		28
Headlights to stay open	1999 November	25	1	39
Hidden headlight repair	2000 May	33		52
Horn relay	2004 May	33	4	121
Instrument lights	2002 November	28	1	93
Left headlight not opening	2001 August	34	4	72
Low track light	2000 November	32	7	61
Radio codes	2003 May	33		105
Radio head unit	2004 August	26	2	123
Radio problem	2003 May	27	4	101
Rear lights	2004 January	28	5	115
Service engine light	2001 February	28	3	63
SES light	2005 May	23	4	139
Stock headlights on 3rd gen	2004 January	34		118
Turn signal bulb	2002 February	28	4	78
Emission Controls				
California smog equipment	1999 February	32	1	26
Fault codes	1998 August	29	1	19
Red catalytic converter	2002 February	28	3	78

SUBJECT/ ARTICLE	ISSUE	ORIGINAL PUBLICATION		PAGE NUMBER
		PAGE	Q & A	THIS ISSUE
Engine/Mechanical				
4th generation headlight fix	1999 November	26		40
403 Olds modifications	2007 February	21	1	154
350 & 400 engine difference	2002 May	29	3	84
'67 original engine	2000 May	28	5	49
'80 Trans Am with 400	2001 February	29	5	64
'81 TA engines	2000 August	29	5	56
Belt replacement	1999 February	33	2	27
Belt squealing	2005 February	22	4	134
Bigger engine	2001 May	29	3	67
Boring out	2002 February	32	1	80
Cadillac engine	2007 February	22	2	155
Engine hoist	1999 May	32	1	34
Engine removal	2002 February	28	2	78
Engine replacement	2002 May	34		92
Engine seal replacement	2000 May	32	1	51
Engine setup	1998 February	28	2	10
Engine swap	1999 November	25	7	39
Engine swap #2	2001 May	29	4	67
Check engine light	2000 August	32	4	57
Check engine light pt. 2	2001 May	29		67
Horsepower buildup	2002 February	32	2	80
Horsepower ratings	2000 February	26	4	43
Idle stall	2000 November	32	1	61
Insulating manifold heat	2004 November	23	2	131
Manifold insulation	1999 February	33	1	27
More horsepower	2000 May	28	3	49
Motor mounts for 400	2002 May	29	5	84
Not starting	2007 May	22	2	158
Olds 403 power	2001 May	32	3	68
Olds 403 specs	2004 August	27	1	124
Olds engine	1999 November	25	5	39
Peak performance	2001 May	32	2	68
Power steering fluid	2003 August	27	4	108
Ram air V engine	2000 August	33		58
Rattling noise	2000 February	27	3	44
RPM surge	2001 August	33	2	71
Running rough	2001 February	28	1	63
Supercharger	2002 November	32	4	94
Starting problems	2001 February	29	1	64
Vortec supercharger	2000 November	33		62
Ticking sound	1999 May	29	2	33

SUBJECT/ ARTICLE	ISSUE	ORIGINAL PUBLICATION		PAGE NUMBER
		PAGE	Q & A	THIS ISSUE
Exhaust				
Aftermarket headers	1999 February	35	1	29
Best Cat-Back exhaust	2002 February	29	3	79
Dual exhaust	2003 February	32	2	98
Edelbrock manifold	2004 January	27	5	114
Edelbrock performer	2001 August	32	4	70
Exhaust manifold bolts	2002 November	32	2	94
Exhaust replacement	2003 August	34		113
Exhaust system replacement	2004 May	28	4	119
Flowmaster	2004 January	33	2	117
Flowmaster exhaust	2002 August	28	3	88
Headers	2002 February	33		81
Headers for a 301	2004 May	28	1	119
Manifolds	2006 August	26	3	149
Muscle car sound	2005 August	21	2	142
Ram Air III exhaust	2001 February	29	2	64
Exterior/Body				
400 hood	2006 May	22	1	146
'78 Formula t-tops	2000 February	27	1	44
'79 decal set	2000 August	32	2	57
'92 model year paint	2000 August	29	1	56
American hatch t-tops	2006 November	21	3	150
Bumper emblem	2000 February	26	1	43
Eagle decal	2005 May	25	1	140
Fiberglass fenders	2005 May	22	1	138
Ground effects	2007 May	22	1	158
GTA emblem	2007 February	26	3	156
Precut striping	2000 May	29	1	50
Rear quarter replacement	2000 November	32	4	61
Rear spoiler replacement	2005 August	22	2	143
Shaker hood scoops	2000 November	29	1	60
Spoilers cracking	2001 May	29	1	67
T-top crack	2002 February	29	4	79
T-top seals	2000 August	28	3	55
Weather-stripping	2002 February	29	1	79
Gauges				
Autometer gauges	2005 February	22	1	134
Gauge Dial repair	1999 November	25	5	39
Generator light	2002 May	32	4	85

SUBJECT/ ARTICLE	ISSUE	ORIGINAL PUBLICATION		PAGE NUMBER
		PAGE	Q & A	THIS ISSUE
General				
14 second car	2001 August	34	1	72
5 Questions	1999 February	29	4	25
'70 1/2 value	2000 February	26	3	43
'78 Redbird	2003 May	26	1	100
'80 pace car	2002 February	32	5	80
'99 Firehawk	2000 November	33	1	62
Acceleration increase	2001 August	34	5	72
Bat out of hell	2001 November	28	1	73
Car storage	1998 February	33		12
Differences in '70 to '73 TAs	1998 August	32		20
F in F-body	2000 August	33		58
First TA production date	2003 May	28	1	102
Make '93 faster	2000 February	26	2	43
NASCAR stickers	2005 February	26	4	136
Performance chips	2000 August	33		58
Performance hints	2002 February	33		81
Performance testing	1999 February	32	2	26
Power steering leak	2002 February	29	5	79
Power to '75 Trans Am	2006 August	22	1	148
Power to wheels	2006 January	22	1	144
Research history of car	2005 February	23		135
Restoration	1998 February	28	1	10
Rocket boost	2003 May	33		105
Rollover ratings	2000 February	28		45
Service manual	2002 May	28	2	83
Setting timing	2001 November	29		74
Stated Value Insurance	1998 August	16		15
Trans Am from Firebird	2005 August	21	1	142
Turbo S.E. difference	2002 May	29	1	84
Windshield washer	2002 February	33		81
Winter storage tips	2001 November	29		74
Windshield washer	2002 February	34		82
Y-82 meaning	2007 August	22	1	160
Interior				
Back window removal	2005 May	23	2	139
Bucket seat replacement	2002 May	28	1	83
Console replacement	2007 February	29	2	157
Cracked dash fixing	2002 November	34		96
Door alignment	2004 May	34		122
Headliner removal	2003 August	33	1	112
Hinges	2005 February	22	2	134

SUBJECT/ ARTICLE	ISSUE	ORIGINAL PUBLICATION		PAGE NUMBER
		PAGE	Q & A	THIS ISSUE
Interior upgrade	2002 November	34		96
Loose windows	1999 November	25	2	39
Parchment seat covers	2005 May	23	5	139
Part Changeability	2001 February	28	2	63
Rear deck replacement	2005 February	26	2	136
Seat belt guide removal	2002 May	29	2	84
Seat color	2006 November	22	1	151
Seat covers	2006 November	21	1	150
Steering wheel emblem	2006 November	26	1	152
Steering wheel removal	2002 February	34		82
Trunk release	2004 August	26	1	123
Window relay	1998 November	28	2	23
Numbers/Identification				
Decode 4th generation VIN	1998 February	25		14
GM Vin Digit Identification	2000 May	35		54
Vin Number Breakdown	1999 November	28		42
Vin Number Breakdown pt. 2	2000 February	32		47
Oil/Lubrication				
The Dirt on oil	1999 May	24		30
Oil changes	2004 August	26	3	123
Oil type	2001 August	33	1	71
Posi oil	2005 August	22	3	143
Synthetic oils	2006 August	26	2	149
Suspension/Handling				
Coil spring replacement	2000 February	27	2	44
Limited slip additive	1999 May	29	1	33
Lowering a 2nd generation	2004 May	34		122
Rack and pinion	2001 August	32	2	70
Shocks	2007 February	26	1	156
Spring spacers	2006 November	21	2	150
Suspension improvements	2005 August	21	3	142
Stock Auburn gear	2001 August	32	3	70
Thunking noise	2001 May	29	2	67
Vibration	2002 May	28	5	83
Vibration on 4th generation	2000 November	33		62
Vibration problem	2002 May	34		92
WS-6 first year	2000 August	32	1	57
WS-6 package	2001 August	32	5	70
WS-7 handling package	2003 August	34		113
WS-7 suspension	2002 May	28	3	83

SUBJECT/ ARTICLE	ISSUE	ORIGINAL PUBLICATION		PAGE NUMBER
		PAGE	Q & A	THIS ISSUE
Tires/Wheels				
'70 TA wheel sizes	2002 May	29	7	84
8 inch rims	2003 May	28	5	102
'92 wheels	2001 February	33	1	66
Center caps	2002 November	32	1	94
Long shank lug nuts	1998 November	28	1	23
Restoring wheels	1998 February	35		14
Refinish rims	2002 May	33	2	91
Restoring wheels	2004 August	34		128
Tire rotation	2000 May	33		52
Tire replacement	2000 August	28	1	55
Tire size	2004 August	34		128
Tires	1999 February	34		28
Tires pt. 2	2004 November	27		133
Transmission/Clutch/Drive Train				
4.10 rear end	2002 May	32	2	90
700R4 transmission	2000 November	32	5	61
Clunking noise	2000 May	28	5	49
Clutch replacement	2000 November	33	2	62
Gears	2006 May	26	1	147
Hurst usage	2001 August	33	3	71
Powerglide transmission	2007 February	21	2	154
Transmission choice	2002 February	33		81
Transmission leakage	2006 August	22	2	148
Transmission service	2000 May	33		52
Transmission swap	2001 May	33		69
Transmission tuning	1998 August	28	1	18
Transmission tuning pt. 2	2004 August	33	1	127